

**GOOD WILL INSTRUMENT CO., LTD.**

**CALIBRATION PROCEDURE**

**LCR METER**

**MODEL: LCR-817/819**

<b>GOODWILL INSTRUMENT CO., LTD.</b>		
<b>APPROVED BY</b>	<b>CHECKED BY</b>	<b>PREPARED BY</b>

TOTAL 16 PAGES  
EXCLUDING COVER PAGE

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	1/16	
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>	<b>PQC SPEC.</b>

Note : LCR-819 => (Test Frequency: MAX:100KHz ) , LCR-817 => (Test Frequency :MAX:10KHz)

Measurement devices:

1. Digital Multimeter    2.DC POWER SUPPLY .
- 3.Resistor Standard kit, QuadTech CALIBRATED PART NO.:1689-9604 (SERIAL:9376462)
- 4.Universal Programmer    5.Resistor Specification Adjusting fixture(Fixture No.:PE-M0-195 ) ,
6. PQC Accuracy check Fixture(22 sets)。  
7.PC(Installed ISP / EPROM software / K Parameter Count Auxiliary Programmer)

<b>Withstanding Test</b>	I/P – FG : 1.5KV / 4.0mA ,1 min .				
1	Outlook check	To check if any scratch on the meter, front panel and case.			
2	Battery Arrangement	<ol style="list-style-type: none"> <li>1. POWER OFF.</li> <li>2. To make sure both ends of the battery on the PCB are open (To check with multimeter that the joint point of positive and negative polar of PCB is high resistance.)</li> <li>3. Set Power Supply to 3V positive and negative terminal to PCB's "+" and "-" as simulation of battery..</li> <li>4. Check if the U314 &amp; U315—28 PIN is 3V. If yes, mounting the battery. Repeat the steps 1 to 4.</li> </ol>			
2	Voltage Confirmation	POWER ON			
		Confirm +12V (SW-PW indication +12V output terminal)	CHECK	+12V approx.	-----
		Confirm -12V (SW-PW indication -12V output terminal)	CHECK	-12V approx.	-----
		Confirm +5V (SW-PW indication +5V output terminal)	SW-PW Voltage adjusting knob	+ 5V ± 0.01V	-----
		Check if the voltage of test point - TP11 is +2.5V .	CHECK	+2.5V approx.	-----
3	Operation Function Confirmation	Confirm if the LCD display is ok ( 240*128 )	CHECK	Display ok	Display ok
		Confirm if the KEY BOARD function is ok.	CHECK	Function ok	Function ok
		Check if the FUNCTION KEY works well.	CHECK	Function ok	Function ok
		<ol style="list-style-type: none"> <li>1. SPEED ( SLOW / MEDI / FAST )</li> <li>2. DISPLAY (VALUE / DELTA% / DALTA )</li> <li>3. MODE ( R/Q , C/D , C/R , L/Q )</li> <li>4. CIRCUIT ( SERIES / PARALL )</li> <li>5. INT / EXT switchable =&gt; “ 7 ”key, ( ON/OFF ) =&gt; “ 8 “ key.</li> <li>6. C.V ( ON/OFF ) =&gt; “ 1 ” key: ( Constant Voltage )</li> <li>7. R.H ( ON/OFF ) =&gt; “ 0 “ key: ( Range Hold )</li> <li>8. AUTO / MANU switchable =&gt; “ STRAT “ key (more than 3 seconds.) .</li> <li>9. PPM switchable =&gt; “ 4 “ key.</li> </ol>			Function ok

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	2/16
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>
					<b>PQC SPEC.</b>





Figure 1

4	LOAD DEFAULT FACTOR Function	<p>Download calibration value: Under the main display, press F5 to enter MENU display, press F4 function key which responses to the function of "CALIBRATION" of the fourth block. Now the display is for secret code input, input <span style="border: 1px solid black; padding: 0 2px;">0712</span> secret code, get into Calibration display, then press F4, the correspond function of "LOAD DEFAULT FACTOR", select "1" confirming key, it will appear a bar, after the bar is filled with dark color, it means the download has been finished. After the bar disappeared, press F5, the exit key, to get back to the main display.(Select "2" to cancel "LOAD DEFAULT FACTOR").</p>	Function ok	Function ok
---	---------------------------------------	---	-------------	-------------

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	3/16
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>



<p>5</p> <p>Zero Adjustment (Please set the standard kit of OPEN/SHORT to the Calibration fixture according to the Calibration drawing of tested unit.</p>	<ul style="list-style-type: none"> <li>● OPEN: Connect measured terminal to OPEN standard kit, press F5(MENU) entering MENU display. The first block of display is “OFFSET” function, which is correspond to F1 key, press F1 to appear another display, the first block of the display is “CAP OFFSET” function, correspond to F1 key, press again F1 to appear a bar. After the bar is filled with dark color, whether the OPEN function is completed or not, it will be displaying “OK” or “FAIL” signal at the upper right corner to indicate its status. Check if it is completely open.</li> <li>● SHORT: Connect measured terminal to SHORT standard kit, press F5 (MENU) entering MENU display. The first block of display is “OFFSET” function, which is correspond to F1 key, press F1 to appear another display, the first block of the display is “R/L OFFSET” function, correspond to F1 key, press again F1 to appear a bar. After the bar is filled with dark color, whether the SHORT function is completed or not, it will be displaying “OK” or “FAIL” signal at the upper right corner to indicate its status. Check if the terminal is completely short. After the bar is disappeared, press F5 back to main display.</li> </ul> <p>Please refer to the following Figure 2: Summary of zeroing menu</p>	<p>C/R MODE Display C=± 0.0003 (nF)</p> <p>R/Q MODE Display R=± 0.0010 ( )</p>
--	---	---

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	4/16
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>
					<b>PQC SPEC.</b>

**L 1.2345H**  
**Q 0.6789**

TESTING

F : 1.000 kHz    R.H OFF  
V : 1.000 V     C.V OFF

**AUTO**    MANU    INT.B OFF

**SPEED**  
SLOW

**DISPLAY**  
VALUE

**MODE**  
L/Q

**CIRCUIT**  
SERIES

**MENU**

**Test Condition:**

Test voltage=1V  
Test frequency=1KHz  
Test speed = SLOW  
R.H = OFF  
C.V = OFF

**CAP. R/L OFFSET**

**SET SORT**

**SET PARAMETER**

**CALIBRATION**

**OFFSET**

**SORT**

**SETTING**

**CALBRAT**

**EXIT**

Press **F1** key to the zeroing menu

**OPEN TEST**

**SHORT TEST**

**CAP**  
**OFFSET**

**R/L**  
**OFFSET**

**EXIT**

Press **F1** KEY for open test

Press **F2** KEY for short test

Figure 2: Summary of zeroing menu

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	5/16
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>

6	<p>Calibrating RANGE 1 R4 calibrator: R=24.897 Q=8 Please set the R4 standard kit to the Calibration fixture according to the Calibration drawing of tested unit.</p>	<p>a. Take R4 calibration standard kit from calibration cabinet, put to the position shown as attached drawing. Measure and record R resistance value.</p> <p>b. F5 F4 0712 F1 F1</p> <p>c. Input standard value to the standard kit, press enter.</p> <p>d. Press F5 back to main display, after 30 seconds observation, confirm whether the R value is meet the standard value.  <u>ADJ =&gt; 1KHz :LCR-819 &amp; LCR-817 : ( 24.897 ± 1 count ) .</u>                      If yes, proceed next step e, if not, repeat the steps from a to d.</p> <p>e. Set frequency at 100kHz for LCR-819, 10kHz for LCR-879, after 30 seconds observation, confirm whether the R value is met the standard value.  <u>ADJ =&gt; LCR-819:100kHz, LCR-879:10kHz : 24.896 24.898</u>                      If yes, jump to step 7 to calibrate RANGE 2, if not, continue the step f.</p> <p>f. F5 F4 0712 F2 F1 , start to calculate k value with the formula as below:                      LCR-819 :k1= ( 100kHz measured value - 24.897 ) ÷ 0.01                      LCR-817 :k1= ( 10kHz measured value - 24.897) ÷ 0.00001  <u>K=K+k1</u>  <u>Remark : Above calculated formula can count out accuracy as attached drawing.</u></p> <p>g. Input new k value, press ENTER key.</p> <p>h. Press F5 back to main display, after 30 seconds observation, confirm R value as:  <u>LCR-819: 24.896 24.898 .</u>                      If the reading value draft&gt; 24.896 24.898, then it is for LCR-817.                      (LCR-817 main program must be re-written from item 4. LOAD DEFAULT FACTOR function)  <u>LCR-817:10kHz , after 30 seconds observation, confirm R value as: 896 24.898</u>                      If yes, continue step j, if not, repeat steps f~h.</p> <p>i. Set frequency at 1kHz, repeat steps b~h</p>
---	---	--

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	<b>6/16</b>
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>
					<b>PQC SPEC.</b>

The screenshot shows a software window titled "LCR-819/LCR-817 高频之k参数计算". The interface includes the following elements and callouts:

- 1. Select tested model:** Radio buttons for "LCR-817" and "LCR-819".
- 2. Input high frequency reading value:** A text box containing "24.895" next to the label "100KHz 测量读值".
- 3. Input high frequency original K parameter:** A text box containing "5.5879" next to the label "100KHz 原 K 参数".
- 4. Press calculation knob to calculate k value:** A button labeled "校正 K 参数计算".
- Display correct high frequency k parameter:** A text box containing "5.3880" next to the label "100KHz 校正 K 参数".
- Display the information of calibration specification:** A text box containing "精确测试读值为: 24.898Ω - 24.898Ω (LCR-819)".
- Program version:** A text box containing "VER 1.3".
- Program termination:** A button labeled "Exit".

Additional interface elements include a "校正机型为 LCR-819" label, a "RANGE 1" button, and a "重算" (Recalculate) button.

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	7/16
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>

7	Calibrating RANGE 2  R3 Calibrator: R=374.02 Q=4 (Please set the R3 standard kit to the Calibration fixture according to the Calibration drawing of tested unit. )	a. Take R3 calibration standard kit from calibration cabinet, put to the position shown as attached drawing. Measure and record R resistance value. b. F5 F4 0712 F1 F2 c. Input standard value to the standard kit, press enter. d. Press F5 back to main display, after 30 seconds observation, confirm whether the R value is meet the standard value. ADJ => 1KHz :LCR-819 & LCR-817 : ( 374.02± 1 count ) . If yes, proceed next step e, if not, repeat the steps a~ d. e. Set frequency at 100kHz for LCR-819, 10kHz for LCR-817, after 30 seconds observation, confirm whether the R value is meet the standard value. ADJ => LCR-819:100kHz, LCR-817:10kHz : 374.00~374.04 If yes, jump to step 7 to calibrate RANGE 3, if not, continue the step f. f. F5 F4 0712 F2 F2 , start to calculate k value with the formula as below: LCR-819 :k1= ( 100kHz measured value - 374.02 ) ÷ 0.14 LCR-817 :k1= ( 10kHz measured value - 374.02) ÷ 0.001 K=K+k1 Remark : Above calculated formula can count out accuracy as attached drawing. g. Input new k value, press ENTER key. h. Press F5 back to main display, after 30 seconds observation, confirm R value as: LCR-819: 374.00~374.04 . If the reading value draft> 374.00~374.04, then it is for LCR-817. (LCR-817 main program must be re-written from item 4. LOAD DEFAULT FACTOR function) LCR-817:10kHz , after 30 seconds observation, confirm R value as: 374.00~374.04 If yes, continue step j, if not, repeat steps f~h. i. Set frequency at 1kHz, repeat steps b~h
---	--	--



# ADJUSTMENT PROCEDURE

MODEL:	LCR-817/819	Doc. No.		Page:	8/16	
NO.	ITEM	SPEC.	CONDITION	ADJ. POINT	ADJ. SPEC.	PQC SPEC.

The screenshot shows a software interface for calculating the K parameter at high frequencies. It includes the following elements:

- Model Selection:** Radio buttons for 'LCR-817' and 'LCR-819'. The 'LCR-819' option is selected.
- Calibration Model:** A label '校正機型為' followed by the text 'LCR-819'.
- Measurement Data:** A label '100KHz 測量讀值' with a text box containing '373.6' and a 'RANGE 2' button.
- Original Parameter:** A label '100KHz 原 K 参数' with a text box containing '-5'.
- Buttons:** '校正 K 参数计算' (Calculate K parameter) and '重算' (Recalculate).
- Result:** A label '100KHz 校正 K 参数' with a text box containing '-7.9999'.
- Confirmation:** A text box stating '请确认测试读值为: 374.00Ω - 374.03Ω (LCR-819)'. Below it is a 'VER 1.3' label and an 'Exit' button.

The calibration procedure is the same as RANGE-1

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	<b>9/16</b>
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>

8	Calibrating RANGE 3  <u>R2 Calibrator:</u> R=5.9665 Q=-12 (Please set the R2 standard kit to the Calibration fixture according to the Calibration drawing of tested unit. )	a. Take R2 calibration standard kit from calibration cabinet, put to the position shown as attached drawing. Measure and record R resistance value. b. F5 F4 0712 F1 F3 c. Input standard value to the standard kit, press enter. d. Press F5 back to main display, after 30 seconds observation, confirm whether the R value is met the standard value. ADJ => 1KHz :LCR-819 & LCR-817 : ( 5.9665± 1 count ) . If yes, proceed next step e, if not, repeat the steps a~ d. e. Set frequency at 100kHz for LCR-819, 10kHz for LCR-817, after 30 seconds observation, confirm whether the R value is meet the standard value. ADJ => LCR-819:100kHz: 5.9660~5.9666, LCR-817:10kHz : 5.9663~5.9667 If yes, jump to step 7, if not, continue the step f to calibrate RANGE 4. f. F5 F4 0712 F2 F3 , start to calculate k value with the formula as below: LCR-819 :k1= ( 100kHz measurement value - 5.9663 ) ÷ 0.00231 LCR-817 :k1= ( 10kHz measurement value - 5.9665 ) ÷ 0.00002 $K=K+k1$ Remark : Above calculated formula can count out accuracy as attached drawing. g. Input new k value, press ENTER key. h. Press F5 back to main display, after 30 seconds observation, confirm R value as: LCR-819: 5.9660~5.9666 If the reading value draft> 5.9660~5.9666, then it is for LCR-817. (LCR-817 main program must be re-written from item 4. LOAD DEFAULT FACTOR function) LCR-817:10kHz , after 30 seconds observation, confirm R value as: 5.9663~5.9667 If yes, continue step j, if not, repeat steps f~h. i. Set frequency at 1kHz, repeat steps b~h
---	---	---

# ADJUSTMENT PROCEDURE

MODEL:	LCR-817/819	Doc. No.		Page:	10/16
NO.	ITEM	SPEC.	CONDITION	ADJ. POINT	ADJ. SPEC.
					PQC SPEC.

LCR-819/LCR-817 高頻之K參數計算

---

待測機型選擇

LCR-817                       LCR-819

---

校正機型為                      LCR-819

---

100KHz 測量讀值	5.965	RANGE 3
100KHz 原 K 參數	-50	

---

100KHz 校正 K 參數	-50.5627
----------------	----------

請確認測試讀值為 : 5.9680KΩ - 5.9686KΩ (LCR-819)

The calibration procedure is the same as RANGE-1

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	<b>11/16</b>
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>

9	Calibrating RANGE 4  R1 Calibrator: R=95.357 Q=-272 (Please set the R1 standard kit to the Calibration fixture according to the Calibration drawing of tested unit.)	a. Take R1 calibration standard kit from calibration cabinet, put to the position shown as attached drawing. Measure and record R resistance value. b. F5 F4 0712 F1 F4 c. Input standard value to the standard kit, press enter. d. Press F5 back to main display, after 30 seconds observation, confirm whether the R value is meet the standard value. ADJ => 1KHz :LCR-819 & LCR-817 : ( 95.357± 1 count ) . If yes, proceed next step e, if not, repeat the steps a~ d. e. Set frequency at 20kHz for LCR-819, 10kHz for LCR-817, after 30 seconds observation, confirm whether the R value is meet the standard value. ADJ => LCR-819: 20kHz: 95.342~95.350, LCR-817:10kHz : 95.348~95.352 If yes, the calibration is finished, if not, continue the step f. f. F5 F4 0712 F2 F4 , start to calculate k value with the formula as below: LCR-819 :k1= ( 20kHz measured value - 95.346 ) ÷ 0.0015 LCR-817 :k1= ( 10kHz measured value - 95.350 ) ÷ 0.00038 K=K+k1 Remark : Above calculated formula can count out accuracy as attached drawing. g. Input new k value, press ENTER key. h. Press F5 back to main display, after 30 seconds observation, confirm R value as: LCR-819: 95.342~95.350 If the reading value draft> 95.342~95.350, then it is for LCR-817. (LCR-817 main program must be re-written from item 4. LOAD DEFAULT FACTOR function) LCR-817:10kHz , after 30 seconds observation, confirm R value as: 95.348~95.352 If yes, continue step j, if not, repeat steps f~h. i. Set frequency at 1kHz, repeat steps b~h
---	--	--

# ADJUSTMENT PROCEDURE

MODEL:	LCR-817/819	Doc. No.		Page:	12/16	
NO.	ITEM	SPEC.	CONDITION	ADJ. POINT	ADJ. SPEC.	PQC SPEC.

LCR-819 / LCR-817 高频之K参数计算

待测机型选择

LCR-817       LCR-819

校正机型为      LCR-819

20KHz 测量读值      94.5      RANGE 4

20KHz 原 K 参数      -272

校正 K 参数计算      重算

20KHz 校正 K 参数      -836.0004

请确认测试读值为 : 95.342kΩ - 95.350kΩ (LCR-819)

VER 1.3      Exit

The calibration procedure is the same as RANGE 1

# ADJUSTMENT PROCEDURE

MODEL:	LCR-817/819	Doc. No.		Page:	13/16	
NO.	ITEM	SPEC.	CONDITION	ADJ. POINT	ADJ. SPEC.	PQC SPEC.

PQC INSPECTION ITEM					
10	Measured Voltage setting	Measured Voltage: 5mV ~ 1.275V with 5mV interval. (Refer to Figure 4, press MENU SET PARAMETER VOLT )	Function ok	Function ok	
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> </div> <div style="width: 45%;"> </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> </div> <div style="width: 45%;"> </div> </div>					
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> </div> <div style="width: 45%;"> </div> </div> <p style="text-align: center;">Figure 5. Inputs of test frequency</p>					
11	Measured Frequency setting	Refer to Figure 5, press " FREQ " key, then, input measured frequency, press ENTER key. LCR-819 working frequency : 12Hz ~ 100KHz LCR-817 working frequency : 12Hz ~ 10KHz	Function ok	Function ok	

Figure 4. Programming of test voltage.

Figure 5. Inputs of test frequency

## ADJUSTMENT PROCEDURE

MODEL:	LCR-817/819	Doc. No.		Page:	14/16	
NO.	ITEM	SPEC.	CONDITION	ADJ. POINT	ADJ. SPEC.	PQC SPEC.
12	Measured Status Record Setting		Refer to Figure 4, press MENU SET PARAMETER MEMORY 1. Press MEMORY key, select (1)RECALL/(2)STORT, then input Recall code and Memory code. 2. Totally 100 memory sets.		Function ok	Function ok
13	Average Value Output		Refer to Figure 4, press MENU SET PARAMETER AVGE , after AVGE key being pressed, input average numbers of times of measured value.		Function ok	Function ok
14	INT DCBAIS		1. Under main display, press number “7” BIAS key and “8” ON/OFF key, switching on INT B. 2. Measured both terminals “+” and “-” voltage of FORCE with DC measured range of digital multimeter.(No load)	CHECK	+2V± 5%	+2V± 5%
15	EXT DCBIAS		1. Under main display, press number “7” BIAS key and “8” ON/OFF key, switching on INT B 2. Input DC voltage to EXT BIAS terminal. ( MAX: 30VDC / 200mA ). 3. Measured both terminals “+” and “-” voltage of FORCE with DC measured range of digital multimeter.(No load)	CHECK	Same as input voltage	Same as input voltage

# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	15/16
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ. SPEC.</b>
					<b>PQC SPEC.</b>

Press the numerical **7** key to select either internal or external bias voltage



Press the numerical **8** key to turn either internal or external bias voltage on or off.

BIAS key:

INT / EXT BIAS Voltage switching.

ON / OFF (8) key:

BIAS Voltage output switching.



Indication of internal or external bias voltage

Figure 6. Selection of "BIAS" voltage

16	Standard Tested Unit Setting	<ol style="list-style-type: none"> <li>1. The setting describes as follows:</li> <li>2. Co-operate with DISPLAY function key, (VALUE / DELTA% / DALTA ) can get the error percentage and error value.</li> </ol>	Function ok	Function ok
----	---------------------------------	--	-------------	-------------



# ADJUSTMENT PROCEDURE

<b>MODEL:</b>	LCR-817/819	<b>Doc. No.</b>		<b>Page:</b>	<b>16/16</b>
<b>NO.</b>	<b>ITEM</b>	<b>SPEC.</b>	<b>CONDITION</b>	<b>ADJ. POINT</b>	<b>ADJ.SPEC.</b>
					<b>PQC SPEC.</b>

**L 1.2345H**

**Q 0.6789**

TESTING

F : 1.000 kHz    R.H OFF

V : 1.000 V     C.V OFF

**AUTO**    MANU    INT.B OFF

SPEED

SLOW

DISPLAY

VALUE

MODE

L/Q

CIRCUIT

SERIES

MENU

1. Select MENU key, enter Function key selection..

Press menu key

**CAP. R/L OFFSET**    OFFSET

**SET SORT**            SORT

**SET PARAMETER**    SETTING

**CALIBRATION**        CALBRAT

EXIT

Press F2 key to the sort menu

2. Select SORT key, enter SORT MANU.

**NOM.VAL = 77.000pF**    NOM. VAL

24.870

**D/Q FOR PPM= 64 PPM**    D/Q PPM

64

EXIT

Press F1 key to input the nominal value

3. Select NOM.VAL key, set standard value for the tested unit.
4. Select D/Q PPM key, set standard D/Q value for the tested unit.
5. Press EXIT key, back to main display of measurement.

**17. Accuracy Confirmation for each range**

Note:

- A. Please be according to the attached inspection data to compare the test distortion value with the model of HP4284A and LCR-817/819(based on HP4284A test value, compare the error distortion value with LCR-817/819).
- B. Before testing HP4284A, re-operate the OPEN/SHORT zero adjustment( not necessary for every frequency point to do the zero adjustment procedure.)
- C. For the LCR-817/819, every frequency points listed must do the zero adjustment.
- D. The tested unit waiting for confirming the specification must not be piled up together, keep the distance for every units about 10 cm more and put on the cover for testing.